



INTERNATIONAL ROAD DYNAMICS INC.

702 - 43rd Street East Saskatoon, SK CANADA S7K 3T9

Ph: (306) 653-6600 Fax: (306) 242-5599 www.irdinc.com

- Site Report -

Date: June 5, 2009

IRD Sales Order: 11014

To: Greg Felsing

From: Bryan Knight

Project Name/Location: New Mexico, I-25 N mp 35

Service Date(s): May 22 2009

Job Description: LTPP Maintenance Visit

Work Completed:

- Performed visual inspection of in road sensors. No issues noted.
- Recorded electrical readings of in road sensors. All readings are within spec.
- Performed housekeeping on the equipment cabinet and surrounding area.
- Site appears to be fully functional.

Work Remaining:

Schedule Include Estimate to Complete (on-track, ahead, behind):

Parts Used:

Pre-mature Equipment Failure:

Mileage / Travel Time: Total Onsite: 3hrs

Safety Concerns:

Issues Related to Sub-Contractors:

Other Notes:

Action Items:

Item	Action Required	Ownership
1.		
2.		
3.		
4.		